

## LIFTING STEEL LIDS

(USE POLYESTER SLINGS TO PREVENT PAINT DAMAGE)


## **POLYESTER SLINGS**

## NOTE 1

<u>DO NOT</u> USE STEEL CHAINS FOR LIFTING, THE USE OF POLYESTER SLINGS IS HIGHLY RECOMMENDED TO PREVENT CHIPPING AND SCRATCHING OF PAINT ON ALL SUTERA STEEL LIDS.

## NOTE 2

THREE (3) COMPLETE SETS OF THE BELOW LISTED ITEMS ARE REQUIRED TO LIFT SUTERA STEEL LIDS.







ITEM No.1: POLYESTER SLING FOR LIFTING (6 FT. LENGTH min. 6,200 lbs. CAPACITY)



ITEM No.2: SCREW PIN SHACKLE FOR LIFTING (min. 7,100 lbs. CAPACITY)



ITEM No.3: EYE HOOK FOR LIFTING w SPRING LATCH (min. 8,800 lbs. CAPACITY)